

Date: July 18, 2014

Subject: Obsolescence of Oil Bath Hub/Drums

Due to low volume and customer demand, Dexter Axle is eliminating the oil bath version for 5-bolt and 6-bolt hubs on axle models D52, D60, #11, and #12. These hubs will no longer have the oil fill hole drilled into them, however the 8-bolt oil bath option will continue to be available.

A new screw-in oil cap with the oil fill in the end of the cap is now available, similar to other Dexter oil cap offerings. The new oil cap replacement kit is K71-747-00.



The following parts will be maintained as service replacement parts until the inventory is depleted.

DX Part Number	Description
008-174-06	W-D 5 bolt demountable
008-201-06	Hub/drum 655 cups & studs for LM67010

Please contact your Dexter sales engineer if you have additional questions or need further assistance.



Rick Kapsa
Market Manager